

2326Z 31 MAR 65

SECRET

1	Cons	9
2		10
3	DEF	11
4	FEED	12
5		13
6	CL	14
7	INTEL	15
8	RB	16

TO : DIRECTOR
25X1A

FROM : [REDACTED]

ACTION:

INFO :

ROUTINE

IN-79625

OSA 1-20

25X1A

25X1A TOP: 2356Z 31 MAR 65

TO : [REDACTED] INFO

CITE [REDACTED] 1189

25X1A IDEALIST [REDACTED] COMMO

25X1A 1. FOLL [REDACTED] READOUTS RECORDED DURING MSN

25X1A 0085G, 30 MARCH 1965, [REDACTED] ALL TIMES ZULU

1845 TAKE OFF. ALL OKAY

1855 ABORT DUE MALFUNCTIONING VOR.

2146 TAKE OFF, ALL OKAY

2154 40 TO 50M, ALL OKAY

2200 ALL OKAY

2300 B/W TRANSMISSION TOO WEAK TO READ.

2400 ALL OKAY

31/0100Z ALL OKAY

0200 ALL OKAY

0300 ALL OKAY

0339 AC GEN OFF, BELOW 60M

0342 40 TO 50M

0349 VOICE CONTACT QRM4 BOTH WAYS. A/C WILL BE DOWN

AT 0405Z.

GROUP 1
EXCLUDED FROM AUTO-
MATIC DOWNGRADING

25X1A

██████████ 189 (IN 79625)

S E C R E T

PAGE TWO

25X1A 2. FOLL ██████████ READOUTS RECORDED DURING MSN

25X1A 0095G, 31 MARCH 1965, ██████████ KCS. ALL TIMES ZULU.

1800 TAKE OFF B/W TRANSMISSION TOO WEAK TO READ.

1807 B/W TRANSMISSION TOO WEAK TO READ.

1815 ALL OKAY

25X1A 1816 VOICE CONTACT BETWEEN ██████████ AND A/C QRK4
BOTH WAYS.

1915 ALL OKAY. VOICE CONTACT QRK4 BOTH WAYS.

2015 ALL OKAY.

2115 ALL OKAY. VOICE CONTACT QRK3 BOTH WAYS.

NO FURTHER TRANSMISSIONS HEARD AFTER 2115 CONTACT.

END OF MSG

S E C R E T